

## Spreading glaze on donuts with vibration

### VTB 5-8

**Challenge:** Distribute glaze on donuts consistently while donuts are conveyed on a conveyor

**Solution:** A pneumatically driven compaction table is located beneath the top strand of the conveyor belt to vibrate the donuts.

